

PART #SBM0912

MASSEY 9500

SUNNYBROOK
COMBINE
PARTS

ALL CROP
CONCAVE

NEED ASSISTANCE

780.789.3855
info@sunnybrookwelding.com



HARD THRESH SET-UP



EASY THRESH SET-UP



MASSEY 9500 ALL CROP

SBM0912 PARTS BREAKDOWN



First Position

Max thresh (boronized) has more but smaller holes with helical bars for our best threshing action. Insert is reversible as the helical bars wear allowing double the life of the insert.



SBM0900BB

Second Position

Max thresh (boronized) & Maxthresh regular with helical bars and slightly larger holes than the boron max thresh, allowing partial separation. Insert is reversible as the helical bars wear allowing double the life of the insert.



SBM0900B



SBM0900BB

Third Position

Max thresh regular with helical bars and slightly larger holes than the boron max thresh, allowing partial separation. Insert is reversible as the helical bars wear allowing double the life of the insert.



SBM0900B

Fourth Position

The Standard Thresh insert provides threshing, but it is less aggressive than our helical bar style. Standard Thresh Insert is designed to balance threshing and separating and is typically used in the middle of a concave set to transition materials or where a less aggressive thresh is desired. Individually replaceable.



SBM0900C



SBM0900B

Fifth Position

Round bar insert (description below) & Standard thresh insert (description above).



SBM0900D



SBM0900C

Sixth Position

The Round bar insert is mainly a separating insert although it does offer a minimal amount of threshing action. More rows of this style would be used in a setup for corn or crops requiring minimal threshing.



SBM0900D

**Single Frame without inserts
SMB0900**

